

State of Utah DEPARTMENT OF NATURAL RESOURCES DIVISION OF OIL, GAS AND MINING

Michael O. Leavitt Governor Kathleen Clarke

Executive Director

Lowell P. Braxton
Division Director

1594 West North Temple, Suite 1210 PO Box 145801 Salt Lake City, Utah 84114-5801 801-538-5340 801-359-3940 (Fax)

801-538-7223 (TDD)

INSPECTION REPORT

Partial XXX	Complete _	Exp	oloration	
Inspection Date:	02/19/2002/	Time:	12:00 to	1:00
	st Inspection:			

Mine Name: <u>Hidden Valley Mine</u>	County: <u>Emery</u>	Permit Number: <u>C/015/007</u>		
Permittee and/or Operator's Name: Consolidation Coal Company				
Business Address: P.O. Box 566, S	Sesser IL 62884/P.O. Box	527, Emery, Utah 84522		
Company Official(s): Seth McCourt	Federal Official(s):	None		
State Official(s): Susan White, LeRoy Mead (DWR), and Chris Colt (DWR)				
Weather Conditions: Cloudy and Cold				
Type of Mining Activity: Underground XXX Surface Prep Plant Other				
Existing Acreage: Permitted 960 Disturbed 7 Regraded Seeded Seeded				
Status: Active				

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For <u>complete inspections</u> provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
 - b. For <u>partial inspections</u> check only the elements evaluated.
- 2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

		EVALUATED	N/A	COMMENTS	NOV/ENF
1.	PERMITS, CHANGE, TRANSFER, RENEWAL, SALE	[X]		[X]	
2.	SIGNS AND MARKERS	[X]		[X]	
3.	TOPSOIL		\Box	\Box	
4.	HYDROLOGIC BALANCE:				
a.	DIVERSIONS	[X]	\Box	[X]	
b.	SEDIMENT PONDS AND IMPOUNDMENTS	\Box			
c.	OTHER SEDIMENT CONTROL MEASURES	ĹĬ	\Box		\Box
d.	WATER MONITORING	\Box			
e.	EFFLUENT LIMITATIONS	\Box	\Box	\Box	
5.	EXPLOSIVES				
6.	DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES				\Box
7.	COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS			\Box	
8.	NONCOAL WASTE	\Box	\Box		
9.	PROTECTION OF FISH, WILDLIFE AND RELATED				
	ENVIRONMENTAL ISSUES	[X]		[X]	\Box
10.	SLIDES AND OTHER DAMAGE	\Box	\Box		
11.	CONTEMPORANEOUS RECLAMATION			\Box	\Box
12.	BACKFILLING AND GRADING	\Box	\Box	\Box	
13.	REVEGETATION	\Box	\Box		\Box
14.	SUBSIDENCE CONTROL	\Box		\Box	
15.	CESSATION OF OPERATIONS	\Box	\Box	\Box	
16.	ROADS:				
a.	CONSTRUCTION/MAINTENANCE/SURFACING	\Box	\Box	\Box	
b.	DRAINAGE CONTROLS	\Box		\Box	\Box
17.	OTHER TRANSPORTATION FACILITIES	\Box		\Box	
18.	SUPPORT FACILITIES/UTILITY INSTALLATIONS	\Box			\Box
19.	AVS CHECK (4th Quarter- April, May, June)	\Box	\Box	. 🛄	\Box
20.	AIR QUALITY PERMIT		\Box		
21.	BONDING & INSURANCE	[]	L1	\Box	\Box

INSPECTION REPORT

(Continuation Sheet)

PERMIT NUMBER: C/015/007	DATE OF INSPECTION: 02/19/2002

(COMMENTS ARE NUMBERED TO CORRESPOND WITH TOPICS LISTED ABOVE)

1. PERMITS, CHANGE, TRANSFER, RENEWAL, SALE

Tim Kirschbaum stated that Seth McCourt, Mining Engineer, should be contacted when the Division is conducting an inspection.

2. SIGNS AND MARKERS

The permit area sign was in place and visible upon entry into the disturbed area.

4A. HYDROLOGIC BALANCE: DIVERSIONS

No evidence of runoff was observed in the drainages.

9. PROTECTION OF FISH, WILDLIFE, AND RELATED ENVIRONMENTAL VALUES

Elk droppings were found in the reclaimed area.

Inspector's Signature: Susan M. White #25 Date: February 20, 2002

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas & Mining.

cc: James Fulton, OSM
Tim Kirschbaum, Consol, Illinois
Steve Behling, Consol, Emery
Price Field office

O:\015007.HID\Compliance\2002\p_0219.doc